




| 1101 Соединяемые контакты | Способ фиксации: X | | | | | |
|---------------------------------|--------------------|------------------|----------------|------------------|------------------|-------------------|
| | Положение рукоятки | | | | | |
| | -90 ⁰ | -45 ⁰ | 0 ⁰ | +45 ⁰ | +90 ⁰ | +135 ⁰ |
| 1 – 2 | - | X | - | - | - | X |
| 3 – 4 | - | X | - | X | - | - |
| 5 – 6 | - | - | - | X | - | - |
| 7 – 8 | - | - | - | - | - | X |
| 9 – 10 | - | - | - | X | - | - |
| 11 – 12 | - | - | - | - | - | X |
| 13 – 14 | - | X | - | - | - | - |
| 15 – 16 | - | - | - | X | - | - |
| 17 – 18 | - | X | - | - | - | - |
| 19 – 20 | - | X | - | - | - | - |
| 21 – 22 | - | - | - | X | - | - |
| 23 – 24 | - | X | - | - | - | - |
| 25 – 26 | - | - | - | X | - | - |
| 27 – 28 | - | - | - | - | - | X |
| 29 – 30 | - | - | - | - | - | X |
| 31 – 32 | - | - | - | - | - | X |
| 33 – 34 | - | X | - | X | - | X |
| 35 – 36 | - | X | - | - | - | - |
| 37 – 38 | - | - | - | X | - | - |
| 39 – 40 | - | - | - | X | - | - |
| 41 – 42 | - | - | - | - | - | X |
| 43 – 44 | - | - | - | - | - | X |




| 1102 Соединяемые контакты | Способ фиксации: X | | | | | |
|---------------------------------|--------------------|------------------|----------------|------------------|------------------|-------------------|
| | Положение рукоятки | | | | | |
| | -90 ⁰ | -45 ⁰ | 0 ⁰ | +45 ⁰ | +90 ⁰ | +135 ⁰ |
| 1 – 2 | - | - | - | X | - | - |
| 3 – 4 | - | X | - | - | - | - |
| 5 – 6 | - | X | - | X | - | - |
| 7 – 8 | - | - | - | - | - | X |
| 9 – 10 | - | - | - | - | - | X |
| 11 – 12 | - | - | - | - | - | X |
| 13 – 14 | - | - | - | X | - | - |
| 15 – 16 | - | - | - | X | - | - |
| 17 – 18 | - | X | - | - | - | - |
| 19 – 20 | - | - | - | - | - | X |
| 21 – 22 | - | - | - | - | - | X |
| 23 – 24 | - | - | - | - | - | X |
| 25 – 26 | - | - | - | - | - | X |
| 27 – 28 | - | - | - | - | - | X |
| 29 – 30 | - | X | - | X | - | - |
| 31 – 32 | - | - | - | X | - | - |
| 33 – 34 | - | X | - | X | - | - |
| 35 – 36 | - | X | - | - | - | - |
| 37 – 38 | - | - | - | - | - | X |
| 39 – 40 | - | - | - | - | - | X |
| 41 – 42 | - | - | - | X | - | - |
| 43 – 44 | - | - | - | - | - | X |




| Соединяемые контакты | Способ фиксации: И | |
|----------------------|---------------------------|------|
| | Положение рукоятки | |
| | 0° | +45° |
| 1 – 2 | X | - |
| 3 – 4 | X | - |
| 5 – 6 | - | X |
| 7 – 8 | - | X |
| 9 – 10 | - | X |
| 11 – 12 | - | X |
| 13 – 14 | - | X |
| 15 – 16 | - | X |
| 17 – 18 | - | X |
| 19 – 20 | - | X |
| 21 – 22 | - | X |
| 23 – 24 | - | X |
| 25 – 26 | - | X |
| 27 – 28 | - | X |
| 29 – 30 | - | X |
| 31 – 32 | - | X |
| 33 – 34 | - | X |
| 35 – 36 | - | X |
| 37 – 38 | - | X |
| 39 – 40 | - | X |
| 41 – 42 | - | X |
| 43 – 44 | - | X |




| Соединяемые контакты | Способ фиксации: Ж, С | | |
|----------------------|------------------------------|----|------|
| | Положение рукоятки | | |
| | -45° | 0° | +45° |
| 1 – 2 | - | - | X |
| 3 – 4 | - | - | X |
| 5 – 6 | X | - | - |
| 7 – 8 | X | - | - |
| 9 – 10 | X | - | - |
| 11 – 12 | X | - | - |
| 13 – 14 | X | - | - |
| 15 – 16 | X | - | - |
| 17 – 18 | X | - | - |
| 19 – 20 | X | - | - |
| 21 – 22 | X | - | - |
| 23 – 24 | X | - | - |
| 25 – 26 | X | - | - |
| 27 – 28 | X | - | - |
| 29 – 30 | X | - | - |
| 31 – 32 | X | - | - |
| 33 – 34 | X | - | - |
| 35 – 36 | X | - | - |
| 37 – 38 | X | - | - |
| 39 – 40 | X | - | - |
| 41 – 42 | X | - | - |
| 43 – 44 | X | - | - |




| Соединяемые контакты | Способ фиксации: Л | | | | |
|----------------------|--------------------|------|----|------|------|
| | Положение рукоятки | | | | |
| | -90° | -45° | 0° | +45° | +90° |
| 1 - 2 | X | - | - | - | - |
| 3 - 4 | - | - | X | - | - |
| 5 - 6 | - | - | - | - | X |
| 7 - 8 | - | - | X | - | - |
| 9 - 10 | - | - | - | - | X |
| 11 - 12 | - | - | - | - | X |
| 13 - 14 | X | - | - | - | - |
| 15 - 16 | - | - | X | - | - |
| 17 - 18 | - | - | - | - | X |
| 19 - 20 | - | - | X | - | - |
| 21 - 22 | - | - | - | - | X |
| 23 - 24 | - | - | - | - | X |
| 25 - 26 | X | - | - | - | - |
| 27 - 28 | - | - | X | - | - |
| 29 - 30 | - | - | - | - | X |
| 31 - 32 | - | - | X | - | - |
| 33 - 34 | - | - | - | - | X |
| 35 - 36 | - | - | - | - | X |
| 37 - 38 | X | - | - | - | - |
| 39 - 40 | X | - | - | - | - |
| 41 - 42 | - | - | X | - | - |
| 43 - 44 | - | - | X | - | - |



| Соединяемые контакты | Способ фиксации: С | | |
|----------------------|--------------------|----|------|
| | Положение рукоятки | | |
| | -45° | 0° | +45° |
| 1 - 2 | - | - | X |
| 3 - 4 | - | X | X |
| 5 - 6 | - | - | X |
| 7 - 8 | - | X | X |
| 9 - 10 | - | - | X |
| 11 - 12 | - | X | X |
| 13 - 14 | - | - | X |
| 15 - 16 | - | X | X |
| 17 - 18 | - | - | X |
| 19 - 20 | - | X | X |
| 21 - 22 | - | - | X |
| 23 - 24 | - | X | X |
| 25 - 26 | - | - | X |
| 27 - 28 | - | X | X |
| 29 - 30 | - | - | X |
| 31 - 32 | - | X | X |
| 33 - 34 | - | - | X |
| 35 - 36 | - | X | X |
| 37 - 38 | - | - | X |
| 39 - 40 | - | X | X |
| 41 - 42 | - | - | X |
| 43 - 44 | - | X | - |



| 1107 Соединяемые контакты | Способ фиксации: Ж | |
|---------------------------------|--------------------|------|
| | Положение рукоятки | |
| | -45° | +45° |
| 1 – 2 | - | X |
| 3 – 4 | - | X |
| 5 – 6 | - | X |
| 7 – 8 | - | X |
| 9 – 10 | - | X |
| 11 – 12 | - | X |
| 13 – 14 | - | X |
| 15 – 16 | - | X |
| 17 – 18 | - | X |
| 19 – 20 | - | X |
| 21 – 22 | - | X |
| 23 – 24 | - | X |
| 25 – 26 | - | X |
| 27 – 28 | - | X |
| 29 – 30 | - | X |
| 31 – 32 | - | X |
| 33 – 34 | - | X |
| 35 – 36 | - | X |
| 37 – 38 | - | X |
| 39 – 40 | - | X |
| 41 – 42 | - | X |
| 43 – 44 | - | X |



| 1108 Соединяемые контакты | Способ фиксации: Г | | | |
|---------------------------------|--------------------|------|------|-------|
| | Положение рукоятки | | | |
| | 0° | +45° | +90° | +135° |
| 1 – 2 | - | - | X | X |
| 3 – 4 | - | X | - | - |
| 5 – 6 | - | - | - | X |
| 7 – 8 | - | - | X | - |
| 9 – 10 | - | X | - | - |
| 11 – 12 | - | - | - | X |
| 13 – 14 | - | - | - | X |
| 15 – 16 | - | X | - | - |
| 17 – 18 | - | - | X | - |
| 19 – 20 | - | - | X | - |
| 21 – 22 | - | - | - | X |
| 23 – 24 | - | X | - | X |
| 25 – 26 | - | X | - | X |
| 27 – 28 | - | - | X | - |
| 29 – 30 | - | - | X | - |
| 31 – 32 | - | X | - | X |
| 33 – 34 | - | X | - | X |
| 35 – 36 | - | - | X | - |
| 37 – 38 | - | - | X | - |
| 39 – 40 | - | X | - | X |
| 41 – 42 | - | X | - | X |

Стр.

11-04

АВКГ 1848


Изм.

Лист


№ докум.

Подпись


Дата




| Соединяемые контакты | Способ фиксации: И | |
|----------------------|---------------------------|------|
| | Положение рукоятки | |
| | 0° | +45° |
| 1 – 2 | - | X |
| 3 – 4 | - | X |
| 5 – 6 | - | X |
| 7 – 8 | - | X |
| 9 – 10 | - | X |
| 11 – 12 | - | X |
| 13 – 14 | - | X |
| 15 – 16 | - | X |
| 17 – 18 | - | X |
| 19 – 20 | - | X |
| 21 – 22 | - | X |
| 23 – 24 | - | X |
| 25 – 26 | - | X |
| 27 – 28 | - | X |
| 29 – 30 | - | X |
| 31 – 32 | - | X |
| 33 – 34 | - | X |
| 35 – 36 | - | X |
| 37 – 38 | - | X |
| 39 – 40 | - | X |
| 41 – 42 | - | X |
| 43 – 44 | - | X |



| Соединяемые контакты | Способ фиксации: М | | | | | | |
|----------------------|---------------------------|------|------|----|------|------|-------|
| | Положение рукоятки | | | | | | |
| | -135° | -90° | -45° | 0° | +45° | +90° | +135° |
| 1 – 2 | - | - | - | - | X | - | - |
| 3 – 4 | - | - | - | - | - | - | X |
| 5 – 6 | - | - | X | - | - | - | - |
| 7 – 8 | X | - | - | - | - | - | - |
| 9 – 10 | - | - | - | - | X | - | - |
| 11 – 12 | - | - | - | - | - | - | X |
| 13 – 14 | - | - | X | - | - | - | - |
| 15 – 16 | X | - | - | - | - | - | - |
| 17 – 18 | - | - | - | - | - | X | - |
| 19 – 20 | - | - | - | X | - | - | - |
| 21 – 22 | - | X | - | - | - | - | - |
| 23 – 24 | - | X | - | - | - | - | - |
| 25 – 26 | - | - | - | X | - | - | - |
| 27 – 28 | - | - | - | - | - | X | - |
| 29 – 30 | - | - | - | - | X | X | - |
| 31 – 32 | - | - | - | - | - | - | X |
| 33 – 34 | - | - | X | X | - | - | - |
| 35 – 36 | X | X | - | - | - | - | - |
| 37 – 38 | - | - | - | - | X | X | - |
| 39 – 40 | - | - | - | - | - | - | X |
| 41 – 42 | - | - | X | X | - | - | - |
| 43 – 44 | X | X | - | - | - | - | - |



| Соединяемые контакты | Способ фиксации: Н | | | | | | | |
|----------------------|---------------------------|------|------|----|------|------|-------|-------|
| | Положение рукоятки | | | | | | | |
| | -135° | -90° | -45° | 0° | +45° | +90° | +135° | +180° |
| 1 – 2 | - | X | - | - | - | - | - | - |
| 3 – 4 | - | X | - | - | - | - | - | - |
| 5 – 6 | - | - | X | - | - | - | - | - |
| 7 – 8 | - | - | X | - | - | - | - | - |
| 9 – 10 | - | - | - | X | - | - | - | - |
| 11 – 12 | - | - | - | X | - | - | - | - |
| 13 – 14 | - | - | - | - | X | - | - | - |
| 15 – 16 | - | - | - | - | X | - | - | - |
| 17 – 18 | - | - | - | - | - | X | - | - |
| 19 – 20 | - | - | - | - | - | X | - | - |
| 21 – 22 | - | - | - | - | - | - | X | - |
| 23 – 24 | - | - | - | - | - | - | X | - |
| 25 – 26 | - | - | - | - | - | - | - | X |
| 27 – 28 | - | - | - | - | - | - | - | X |
| 29 – 30 | X | - | - | - | - | - | - | - |
| 31 – 32 | - | X | - | - | - | - | - | - |
| 33 – 34 | - | - | X | - | - | - | - | - |
| 35 – 36 | - | - | - | X | - | - | - | - |
| 37 – 38 | - | - | - | - | X | - | - | - |
| 39 – 40 | - | - | - | - | - | X | - | - |
| 41 – 42 | - | - | - | - | - | - | X | - |
| 43 – 44 | - | - | - | - | - | - | - | X |



| Соединяемые контакты | Способ фиксации: Ф | | | |
|----------------------|---------------------------|------|----|------|
| | Положение рукоятки | | | |
| | -90° | -45° | 0° | +45° |
| 1 – 2 | - | - | X | - |
| 3 – 4 | X | - | - | - |
| 5 – 6 | - | - | X | - |
| 7 – 8 | X | - | - | - |
| 9 – 10 | - | - | X | - |
| 11 – 12 | X | - | - | - |
| 13 – 14 | - | - | - | X |
| 15 – 16 | - | - | X | - |
| 17 – 18 | X | - | - | - |
| 19 – 20 | - | - | X | - |
| 21 – 22 | - | X | - | - |
| 23 – 24 | - | X | - | - |
| 25 – 26 | - | - | X | - |
| 27 – 28 | X | - | - | - |
| 29 – 30 | - | - | X | - |
| 31 – 32 | - | - | - | X |
| 33 – 34 | - | - | - | X |
| 35 – 36 | - | - | X | - |
| 37 – 38 | X | - | - | - |
| 39 – 40 | - | - | X | - |
| 41 – 42 | - | X | - | - |