




1201 Соединяемые контакты	Способ фиксации: Н							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 – 2	-	-	-	-	-	-	-	X
3 – 4	-	-	-	X	-	-	-	-
5 – 6	X	-	-	-	-	-	-	-
7 – 8	-	-	-	-	X	-	-	-
9 – 10	-	X	-	-	-	-	-	-
11 – 12	-	-	-	-	-	X	-	-
13 – 14	-	-	X	-	-	-	-	-
15 – 16	-	-	-	-	-	-	X	-
17 – 18	-	-	-	-	-	-	-	X
19 – 20	-	-	-	X	-	-	-	-
21 – 22	X	-	-	-	-	-	-	-
23 – 24	-	-	-	-	X	-	-	-
25 – 26	-	X	-	-	-	-	-	-
27 – 28	-	-	-	-	-	X	-	-
29 – 30	-	-	X	-	-	-	-	-
31 – 32	-	-	-	-	-	-	X	-
33 – 34	-	-	-	-	-	-	-	X
35 – 36	-	-	-	X	-	-	-	-
37 – 38	X	-	-	-	-	-	-	-
39 – 40	-	-	-	-	X	-	-	-
41 – 42	-	X	-	-	-	-	-	-
43 – 44	-	-	-	-	-	X	-	-
45 – 46	-	-	X	-	-	-	-	-
47 – 48	-	-	-	-	-	-	X	-




1202 Соединяемые контакты	Способ фиксации: Н							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 – 2	X	-	-	-	-	-	-	-
3 – 4	-	-	-	-	X	-	-	-
5 – 6	-	X	-	-	-	-	-	-
7 – 8	-	-	-	-	-	X	-	-
9 – 10	-	-	X	-	-	-	-	-
11 – 12	-	-	-	-	-	-	X	-
13 – 14	X	-	-	-	-	-	-	-
15 – 16	-	-	-	-	X	-	-	-
17 – 18	-	X	-	-	-	-	-	-
19 – 20	-	-	-	-	-	X	-	-
21 – 22	-	-	X	-	-	-	-	-
23 – 24	-	-	-	-	-	-	X	-
25 – 26	X	-	-	-	-	-	-	-
27 – 28	-	-	-	-	X	-	-	-
29 – 30	-	X	-	-	-	-	-	-
31 – 32	-	-	-	-	-	X	-	-
33 – 34	-	-	X	-	-	-	-	-
35 – 36	-	-	-	-	-	-	X	-
37 – 38	X	-	-	-	-	-	-	-
39 – 40	-	-	-	-	X	-	-	-
41 – 42	-	X	-	-	-	-	-	-
43 – 44	-	-	-	-	-	X	-	-
45 – 46	-	-	X	-	-	-	-	-
47 – 48	-	-	-	-	-	-	X	-




Соединяемые контакты	Способ фиксации: <b>Ж, С</b>		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	X	-	-
3 – 4	-	-	X
5 – 6	X	-	-
7 – 8	-	-	X
9 – 10	X	-	-
11 – 12	-	-	X
13 – 14	X	-	-
15 – 16	-	-	X
17 – 18	X	-	-
19 - 20	-	-	X
21 – 22	X	-	-
23 - 24	-	-	X
25 - 26	X	-	-
27 - 28	-	-	X
29 – 30	X	-	-
31 - 32	-	-	X
33 – 34	X	-	-
35 – 36	-	-	X
37 – 38	X	-	-
39 - 40	-	-	X
41 – 42	X	-	-
43 – 44	-	-	X
45 – 46	X	-	-
47 - 48	-	-	X




Соединяемые контакты	Способ фиксации: <b>С</b>		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	X	-	-
3 – 4	-	-	X
5 – 6	X	-	-
7 – 8	-	-	X
9 – 10	X	-	-
11 – 12	-	-	X
13 – 14	X	-	-
15 – 16	-	-	X
17 – 18	X	-	-
19 - 20	-	-	X
21 – 22	X	-	-
23 - 24	-	-	X
25 - 26	X	-	-
27 - 28	-	-	X
29 – 30	X	-	-
31 - 32	-	-	X
33 – 34	-	X	-
35 – 36	-	X	-
37 – 38	-	X	-
39 - 40	-	X	-
41 – 42	-	X	-
43 – 44	-	X	-
45 – 46	-	X	-
47 - 48	-	X	-




Соединяемые контакты	Способ фиксации: Н							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 – 2	-	-	X	-	-	-	-	-
3 – 4	-	-	-	-	-	-	X	-
5 – 6	-	-	X	-	-	-	-	-
7 – 8	-	-	-	-	-	-	X	-
9 – 10	-	-	X	-	-	-	-	-
11 – 12	-	-	-	-	-	-	X	-
13 – 14	-	-	X	-	-	-	-	-
15 – 16	-	-	-	-	-	-	X	-
17 – 18	-	-	-	-	X	-	-	-
19 – 20	X	-	-	-	-	-	-	-
21 – 22	-	-	-	-	X	-	-	-
23 – 24	X	-	-	-	-	-	-	-
25 – 26	-	-	-	-	X	-	-	-
27 – 28	X	-	-	-	-	-	-	-
29 – 30	-	-	-	-	X	-	-	-
31 – 32	X	-	-	-	-	-	-	-
33 – 34	-	-	X	-	-	-	-	-
35 – 36	-	-	-	-	-	-	X	-
37 – 38	-	-	X	-	-	-	-	-
39 – 40	-	-	-	-	-	-	X	-
41 – 42	-	-	-	-	X	-	-	-
43 – 44	X	-	-	-	-	-	-	-
45 – 46	-	-	-	-	X	-	-	-
47 – 48	X	-	-	-	-	-	-	-



Соединяемые контакты	Способ фиксации: С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	X	-	-
3 – 4	-	-	X
5 – 6	X	-	-
7 – 8	-	-	X
9 – 10	X	-	-
11 – 12	-	-	X
13 – 14	X	-	-
15 – 16	-	-	X
17 – 18	X	-	-
19 – 20	-	-	X
21 – 22	X	-	-
23 – 24	-	-	X
25 – 26	X	-	-
27 – 28	-	-	X
29 – 30	X	-	-
31 – 32	-	-	X
33 – 34	X	-	-
35 – 36	-	-	X
37 – 38	X	-	-
39 – 40	-	-	X
41 – 42	X	-	-
43 – 44	-	-	X
45 – 46	-	X	-
47 – 48	X	-	X



Соединяемые контакты	Способ фиксации: <b>Ф</b>			
	Положение рукоятки			
	-90°	-45°	0°	+45°
1 – 2	X	-	-	-
3 – 4	-	-	X	-
5 – 6	X	-	-	-
7 – 8	-	-	X	-
9 – 10	X	-	-	-
11 – 12	-	-	X	-
13 – 14	X	-	-	-
15 – 16	-	-	X	-
17 – 18	X	-	-	-
19 – 20	-	-	X	-
21 – 22	X	-	-	-
23 – 24	-	-	X	-
25 – 26	-	X	-	-
27 – 28	-	-	-	X
29 – 30	-	X	-	-
31 – 32	-	-	-	X
33 – 34	-	X	-	-
35 – 36	-	-	-	X
37 – 38	-	X	-	-
39 – 40	-	-	-	X
41 – 42	-	X	-	-
43 – 44	-	-	-	X
45 – 46	-	X	-	-
47 – 48	-	-	-	X



Соединяемые контакты	Способ фиксации: <b>Н</b>							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 – 2	-	-	-	X	-	-	-	-
3 – 4	-	-	-	-	-	-	-	X
5 – 6	-	-	-	-	-	X	-	-
7 – 8	-	X	-	-	-	-	-	-
9 – 10	-	X	-	X	-	X	-	X
11 – 12	-	X	-	X	-	X	-	X
13 – 14	-	X	-	-	-	-	-	-
15 – 16	-	-	-	-	-	X	-	-
17 – 18	-	-	-	-	-	-	-	X
19 – 20	-	-	-	X	-	-	-	-
21 – 22	-	-	-	X	-	-	-	-
23 – 24	-	-	-	-	-	-	-	X
25 – 26	-	-	-	-	-	X	-	-
27 – 28	-	X	-	-	-	-	-	-
29 – 30	-	X	-	X	-	X	-	X
31 – 32	-	X	-	-	-	X	-	-
33 – 34	-	X	-	-	-	X	-	-
35 – 36	-	-	-	-	-	X	-	-
37 – 38	-	-	-	X	-	X	-	-
39 – 40	-	X	-	-	-	-	-	X
41 – 42	-	-	-	-	-	-	-	X
43 – 44	-	-	-	X	-	-	-	X
45 – 46	-	-	-	X	-	-	-	X

Стр.

12-04

**АВКГ 1848**


Изм.

Лист


№ докум.

Подпись


Дата




Соединяемые контакты	Способ фиксации: <b>Ф</b>			
	Положение рукоятки			
	-90°	-45°	0°	+45°
1 – 2	-	X	-	-
3 – 4	-	-	X	X
5 – 6	-	-	X	X
7 – 8	-	X	-	-
9 – 10	-	X	-	-
11 – 12	-	-	X	X
13 – 14	-	X	-	-
15 – 16	-	-	X	-
17 – 18	-	-	-	X
19 – 20	-	X	-	-
21 – 22	-	-	X	X
23 – 24	-	-	X	-
25 – 26	-	-	-	X
27 – 28	-	-	X	-
29 – 30	-	-	-	X
31 – 32	-	-	-	X
33 – 34	-	-	-	X
35 – 36	-	-	X	-
37 – 38	-	-	X	-
39 – 40	-	X	-	-
41 – 42	-	X	X	X
43 – 44	-	X	X	X
45 – 46	-	X	X	X
47 – 48	-	X	X	X




Соединяемые контакты	Способ фиксации: <b>Н</b>							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 – 2	-	-	-	X	-	-	-	-
3 – 4	-	-	-	-	-	-	-	X
5 – 6	-	-	-	-	-	X	-	-
7 – 8	-	X	-	-	-	-	-	-
9 – 10	-	X	-	X	-	X	-	X
11 – 12	-	X	-	X	-	X	-	X
13 – 14	-	X	-	-	-	-	-	-
15 – 16	-	-	-	-	-	X	-	-
17 – 18	-	-	-	-	-	-	-	X
19 – 20	-	-	-	X	-	-	-	-
21 – 22	-	-	-	X	-	-	-	-
23 – 24	-	-	-	-	-	-	-	X
25 – 26	-	-	-	-	-	X	-	-
27 – 28	-	X	-	-	-	-	-	-
29 – 30	-	X	-	X	-	X	-	X
31 – 32	-	-	-	-	-	-	-	X
33 – 34	-	-	-	-	-	-	-	X
35 – 36	-	X	-	-	-	-	-	X
37 – 38	-	-	-	X	-	X	-	-
39 – 40	-	-	-	-	-	X	-	-
41 – 42	-	-	-	-	-	X	-	-
43 – 44	-	X	-	-	-	-	-	-
45 – 46	-	-	-	-	-	X	-	-
47 – 48	-	X	-	-	-	-	-	-




Соединяемые контакты	Способ фиксации: X					
	Положение рукоятки					
	-90°	-45°	0°	+45°	+90°	+135°
1 – 2	-	X	-	-	-	-
3 – 4	-	-	-	X	-	-
5 – 6	-	-	-	-	-	X
7 – 8	-	X	-	-	-	X
9 – 10	-	-	-	X	-	-
11 – 12	-	-	-	X	-	-
13 – 14	-	X	-	-	-	X
15 – 16	-	X	-	-	-	X
17 – 18	-	-	-	X	-	-
19 – 20	-	-	-	X	-	-
21 – 22	-	X	-	-	-	X
23 – 24	-	X	-	-	-	X
25 – 26	-	X	-	-	-	X
27 – 28	-	-	-	X	-	-
29 – 30	-	-	-	-	-	X
31 – 32	-	-	-	-	-	X
33 – 34	-	X	-	-	-	-
35 – 36	-	-	-	X	-	-
37 – 38	-	-	-	X	-	-
39 – 40	-	-	-	-	-	X
41 – 42	-	-	-	-	-	X
43 – 44	-	X	-	-	-	-
45 – 46	-	-	-	X	-	X




Соединяемые контакты	Способ фиксации: X					
	Положение рукоятки					
	-90°	-45°	0°	+45°	+90°	+135°
1 – 2	-	-	-	X	-	-
3 – 4	-	X	-	-	-	-
5 – 6	-	X	-	-	-	X
7 – 8	-	-	-	-	-	X
9 – 10	-	-	-	-	-	X
11 – 12	-	-	-	X	-	-
13 – 14	-	-	-	X	-	-
15 – 16	-	-	-	X	-	-
17 – 18	-	X	-	-	-	X
19 – 20	-	X	-	-	-	-
21 – 22	-	-	-	X	-	-
23 – 24	-	X	-	-	-	-
25 – 26	-	X	-	-	-	-
27 – 28	-	X	-	-	-	X
29 – 30	-	-	-	X	-	-
31 – 32	-	-	-	-	-	X
33 – 34	-	-	-	-	-	X
35 – 36	-	-	-	X	-	-
37 – 38	-	X	-	-	-	-
39 – 40	-	-	-	X	-	X
41 – 42	-	-	-	-	-	X
43 – 44	-	-	-	X	-	-
45 – 46	-	-	-	-	-	X
47 – 48	-	-	-	-	-	X




1213 Соединяемые контакты	Способ фиксации: С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	-	X	-
3 – 4	-	-	X
5 – 6	-	X	-
7 – 8	-	-	X
9 – 10	-	X	-
11 – 12	-	-	X
13 – 14	-	X	-
15 – 16	-	-	X
17 – 18	-	X	-
19 – 20	-	-	X
21 – 22	-	X	-
23 – 24	-	-	X
25 – 26	-	X	-
27 – 28	-	-	X
29 – 30	-	X	-
31 – 32	-	-	X
33 – 34	X	-	-
35 – 36	X	-	-
37 – 38	X	-	-
39 – 40	X	-	-
41 – 42	X	-	-
43 – 44	X	-	-
45 – 46	X	-	-
47 – 48	X	-	-



1214 Соединяемые контакты	Способ фиксации: И	
	Положение рукоятки	
	0°	+45°
1 – 2	X	-
3 – 4	-	X
5 – 6	-	X
7 – 8	-	X
9 – 10	-	X
11 – 12	-	X
13 – 14	-	X
15 – 16	-	X
17 – 18	-	X
19 – 20	-	X
21 – 22	-	X
23 – 24	-	X
25 – 26	-	X
27 – 28	-	X
29 – 30	-	X
31 – 32	-	X
33 – 34	-	X
35 – 36	-	X
37 – 38	-	X
39 – 40	-	X
41 – 42	-	X
43 – 44	-	X
45 – 46	-	X
47 – 48	X	X




Соединяемые контакты	Способ фиксации: С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	X	-	-
3 – 4	X	-	-
5 – 6	X	-	-
7 – 8	X	-	-
9 – 10	X	-	-
11 – 12	X	-	-
13 – 14	X	-	-
15 – 16	X	-	-
17 – 18	X	-	-
19 – 20	X	-	-
21 – 22	X	-	-
23 – 24	X	-	-
25 – 26	-	-	X
27 – 28	-	-	X
29 – 30	-	-	X
31 – 32	-	-	X
33 – 34	-	-	X
35 – 36	-	-	X
37 – 38	-	-	X
39 – 40	-	-	X
41 – 42	-	-	X
43 – 44	-	-	X
45 – 46	-	-	X
47 – 48	-	-	X



Соединяемые контакты	Способ фиксации: Н							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 – 2	X	-	-	-	-	-	-	-
3 – 4	-	X	-	-	-	-	-	-
5 – 6	-	-	X	-	-	-	-	-
7 – 8	-	-	-	X	-	-	-	-
9 – 10	-	-	-	-	X	-	-	-
11 – 12	-	-	-	-	-	X	-	-
13 – 14	-	-	-	-	-	-	X	-
15 – 16	-	-	-	-	-	-	-	X
17 – 18	X	-	-	-	-	-	-	-
19 – 20	-	X	-	-	-	-	-	-
21 – 22	-	-	X	-	-	-	-	-
23 – 24	-	-	-	X	-	-	-	-
25 – 26	-	-	-	-	X	-	-	-
27 – 28	-	-	-	-	-	X	-	-
29 – 30	-	-	-	-	-	-	X	-
31 – 32	-	-	-	-	-	-	-	X
33 – 34	X	-	-	-	-	-	-	-
35 – 36	-	X	-	-	-	-	-	-
37 – 38	-	-	X	-	-	-	-	-
39 – 40	-	-	-	X	-	-	-	-
41 – 42	-	-	-	-	X	-	-	-
43 – 44	-	-	-	-	-	X	-	-
45 – 46	-	-	-	-	-	-	X	-
47 – 48	-	-	-	-	-	-	-	X





1217 Соединяемые контакты	Способ фиксации: С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	X	-	-
3 – 4	-	-	X
5 – 6	X	-	-
7 – 8	-	-	X
9 – 10	X	-	-
11 – 12	-	-	X
13 – 14	X	-	-
15 – 16	-	-	X
17 – 18	X	-	-
19 – 20	-	-	X
21 – 22	X	-	-
23 – 24	-	-	X
25 – 26	X	-	-
27 – 28	-	-	X
29 – 30	X	-	-
31 – 32	-	-	X
33 – 34	X	-	-
35 – 36	-	-	X
37 – 38	X	-	-
39 – 40	-	-	X
41 – 42	X	-	-
43 – 44	-	-	X
45 – 46	-	X	-
47 – 48	X	-	X