


1301 Соединяемые контакты	Способ фиксации: X					
	Положение рукоятки					
	-90°	-45°	0°	+45°	+90°	+135°
1 – 2	-	X	-	X	-	-
3 – 4	-	X	-	-	-	-
5 – 6	-	-	-	X	-	X
7 – 8	-	-	-	X	-	-
9 – 10	-	-	-	-	-	X
11 – 12	-	X	-	-	-	X
13 – 14	-	X	-	-	-	-
15 – 16	-	X	-	-	-	-
17 – 18	-	-	-	-	-	X
19 – 20	-	X	-	-	-	-
21 – 22	-	X	-	-	-	-
23 – 24	-	X	-	-	-	-
25 – 26	-	X	-	-	-	-
27 – 28	-	X	-	X	-	-
29 – 30	-	-	-	-	-	X
31 – 32	-	-	-	X	-	X
33 – 34	-	-	-	X	-	-
35 – 36	-	-	-	X	-	-
37 – 38	-	-	-	X	-	-
39 – 40	-	X	-	-	-	-
41 – 42	-	-	-	X	-	-
43 – 44	-	-	-	X	-	-
45 – 46	-	-	-	-	-	X
47 – 48	-	-	-	-	-	X
49 – 50	-	-	-	-	-	X
51 – 52	-	X	-	-	-	-



Соединяемые контакты	Способ фиксации: X					
	Положение рукоятки					
	-90°	-45°	0°	+45°	+90°	+135°
1 – 2	-	X	-	-	-	-
3 – 4	-	-	-	X	-	X
5 – 6	-	-	-	X	-	-
7 – 8	-	-	-	-	-	X
9 – 10	-	X	-	-	-	-
11 – 12	-	-	-	X	-	-
13 – 14	-	-	-	-	-	X
15 – 16	-	X	-	-	-	-
17 – 18	-	-	-	X	-	-
19 – 20	-	-	-	-	-	X
21 – 22	-	-	-	X	-	-
23 – 24	-	X	-	-	-	-
25 – 26	-	-	-	-	-	X
27 – 28	-	-	-	-	-	X
29 – 30	-	-	-	-	-	X
31 – 32	-	-	-	X	-	-
33 – 34	-	X	-	-	-	-
35 – 36	-	-	-	X	-	-
37 – 38	-	X	-	-	-	-
39 – 40	-	-	-	-	-	X
41 – 42	-	-	-	X	-	-
43 – 44	-	-	-	-	-	X
45 – 46	-	X	-	-	-	-
47 – 48	-	-	-	X	-	-
49 – 50	-	X	-	-	-	-
51 – 52	-	-	-	-	-	X