


1401 Соединяемые контакты	Способ фиксации: У			
	Положение рукоятки			
	-45°	0°	+45°	+90°
1 – 2	X	-	-	-
3 – 4	-	-	X	-
5 – 6	-	X	-	-
7 – 8	-	-	-	X
9 – 10	X	-	-	-
11 – 12	-	-	X	-
13 – 14	-	X	-	-
15 – 16	-	-	-	X
17 – 18	X	-	-	-
19 – 20	-	-	X	-
21 – 22	-	X	-	-
23 – 24	-	-	-	X
25 – 26	X	-	-	-
27 – 28	-	-	X	-
29 – 30	-	X	-	-
31 – 32	-	-	-	X
33 – 34	X	-	-	-
35 – 36	-	-	X	-
37 – 38	-	X	-	-
39 – 40	-	-	-	X
41 – 42	X	-	-	-
43 – 44	-	-	X	-
45 – 46	-	X	-	-
47 – 48	-	-	-	X
49 – 50	X	-	-	-
51 – 52	-	-	X	-
53 – 54	-	X	-	-
55 – 56	-	-	-	X



1402 Соединяемые контакты	Способ фиксации: С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	-	-	X
3 – 4	X	-	-
5 – 6	-	-	X
7 – 8	X	-	-
9 – 10	-	-	X
11 – 12	X	-	-
13 – 14	-	-	X
15 – 16	X	-	-
17 – 18	-	-	X
19 – 20	X	-	-
21 – 22	-	-	X
23 – 24	X	-	-
25 – 26	-	-	X
27 – 28	X	-	-
29 – 30	-	-	X
31 – 32	X	-	-
33 – 34	-	-	X
35 – 36	X	-	-
37 – 38	-	-	X
39 – 40	X	-	-
41 – 42	-	-	X
43 – 44	X	-	-
45 – 46	-	-	X
47 – 48	X	-	-
49 – 50	-	-	X
51 – 52	X	-	-
53 – 54	-	-	X
55 – 56	X	-	-