




1601 Соединяемые контакты	Способ фиксации: Ж, С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	-	-	X
3 – 4	X	-	-
5 – 6	-	-	X
7 – 8	X	-	-
9 – 10	-	-	X
11 – 12	X	-	-
13 – 14	-	-	X
15 – 16	X	-	-
17 – 18	-	-	X
19 – 20	X	-	-
21 – 22	-	-	X
23 – 24	X	-	-
25 – 26	-	-	X
27 – 28	X	-	-
29 – 30	-	-	X
31 – 32	X	-	-
33 – 34	-	-	X
35 – 36	X	-	-
37 – 38	-	-	X
39 – 40	X	-	-
41 – 42	-	-	X
43 – 44	X	-	-
45 – 46	-	-	X
47 – 48	X	-	-
49 – 50	-	-	X
51 – 52	X	-	-
53 – 54	-	-	X
55 – 56	X	-	-
57 – 58	-	-	X
59 – 60	X	-	-
61 – 62	-	-	X
63 – 64	X	-	-




Соединяемые контакты	Способ фиксации: Н							
	Положение рукоятки							
	-135°	-90°	-45°	0°	+45°	+90°	+135°	+180°
1 - 2	-	-	-	-	-	-	-	X
3 - 4	-	-	-	X	-	-	-	-
5 - 6	X	-	-	-	-	-	-	-
7 - 8	-	-	-	-	X	-	-	-
9 - 10	-	X	-	-	-	-	-	-
11 - 12	-	-	-	-	-	X	-	-
13 - 14	-	-	X	-	-	-	-	-
15 - 16	-	-	-	-	-	-	X	-
17 - 18	-	-	-	-	-	-	-	X
19 - 20	-	-	-	X	-	-	-	-
21 - 22	X	-	-	-	-	-	-	-
23 - 24	-	-	-	-	X	-	-	-
25 - 26	-	X	-	-	-	-	-	-
27 - 28	-	-	-	-	-	X	-	-
29 - 30	-	-	X	-	-	-	-	-
31 - 32	-	-	-	-	-	-	X	-
33 - 34	-	-	-	-	-	-	-	X
35 - 36	-	-	-	X	-	-	-	-
37 - 38	X	-	-	-	-	-	-	-
39 - 40	-	-	-	-	X	-	-	-
41 - 42	-	X	-	-	-	-	-	-
43 - 44	-	-	-	-	-	X	-	-
45 - 46	-	-	X	-	-	-	-	-
47 - 48	-	-	-	-	-	-	X	-
49 - 50	-	-	-	-	-	-	-	X
51 - 52	-	-	-	X	-	-	-	-
53 - 54	X	-	-	-	-	-	-	-
55 - 56	-	-	-	-	X	-	-	-
57 - 58	-	X	-	-	-	-	-	-
59 - 60	-	-	-	-	-	X	-	-
61 - 62	-	-	X	-	-	-	-	-
63 - 64	-	-	-	-	-	-	X	-




1603 Соединяемые контакты	Способ фиксации: Ж, С		
	Положение рукоятки		
	-45°	0°	+45°
1 – 2	X	-	-
3 – 4	X	-	-
5 – 6	X	-	-
7 – 8	X	-	-
9 – 10	X	-	-
11 – 12	X	-	-
13 – 14	X	-	-
15 – 16	X	-	-
17 – 18	X	-	-
19 – 20	X	-	-
21 – 22	X	-	-
23 – 24	X	-	-
25 – 26	-	-	X
27 – 28	-	-	X
29 – 30	-	-	X
31 – 32	-	-	X
33 – 34	-	-	X
35 – 36	-	-	X
37 – 38	-	-	X
39 – 40	-	-	X
41 – 42	-	-	X
43 – 44	-	-	X
45 – 46	-	-	X
47 – 48	-	-	X
49 – 50	-	X	-
51 – 52	-	X	-
53 – 54	-	X	-
55 – 56	-	X	-
57 – 58	-	X	-
59 – 60	-	X	-
61 – 62	X	-	X
63 – 64	X	-	X




1605 Соединяемые контакты	Способ фиксации: И	
	Положение рукоятки	
	0°	+45°
1 – 2	X	-
3 – 4	X	-
5 – 6	-	X
7 – 8	-	X
9 – 10	-	X
11 – 12	-	X
13 – 14	-	X
15 – 16	-	X
17 – 18	-	X
19 – 20	-	X
21 – 22	X	-
23 – 24	X	-
25 – 26	-	X
27 – 28	-	X
29 – 30	-	X
31 – 32	-	X
33 – 34	-	X
35 – 36	-	X
37 – 38	-	X
39 – 40	-	X
41 – 42	-	X
43 – 44	-	X
45 – 46	X	-
47 – 48	X	-
49 – 50	-	X
51 – 52	-	X
53 – 54	-	X
55 – 56	-	X
57 – 58	-	X
59 – 60	-	X
61 – 62	-	X
63 – 64	-	X




1606 Соединяемые контакты	Способ фиксации: И	
	Положение рукоятки	
	0°	+45°
1 – 2	-	X
3 – 4	-	X
5 – 6	-	X
7 – 8	-	X
9 – 10	-	X
11 – 12	-	X
13 – 14	-	X
15 – 16	-	X
17 – 18	-	X
19 – 20	-	X
21 – 22	-	X
23 – 24	-	X
25 – 26	-	X
27 – 28	-	X
29 – 30	-	X
31 – 32	-	X
33 – 34	-	X
35 – 36	-	X
37 – 38	-	X
39 – 40	-	X
41 – 42	-	X
43 – 44	-	X
45 – 46	-	X
47 – 48	-	X
49 – 50	X	-
51 – 52	X	-
53 – 54	X	-
55 – 56	X	-
57 – 58	X	-
59 – 60	X	-
61 – 62	X	-
63 – 64	X	-



1607 Соединяемые контакты	Способ фиксации: Е		
	Положение рукоятки		
	-90°	0°	+90°
1 – 2	-	X	-
3 – 4	-	X	-
5 – 6	-	X	-
7 – 8	-	X	-
9 – 10	-	X	-
11 – 12	-	X	-
13 – 14	-	X	-
15 – 16	-	X	-
17 – 18	-	X	-
19 – 20	-	X	-
21 – 22	-	X	-
23 – 24	-	X	-
25 – 26	-	X	-
27 – 28	-	X	-
29 – 30	-	X	-
31 – 32	-	X	-
33 – 34	-	X	-
35 – 36	-	X	-
37 – 38	-	X	-
39 – 40	-	X	-
41 – 42	-	X	-
43 – 44	-	X	-
45 – 46	-	X	-
47 – 48	-	X	-
49 – 50	-	X	-
51 – 52	-	X	-
53 – 54	-	X	-
55 – 56	-	X	-
57 – 58	-	X	-
59 – 60	-	X	-
61 – 62	-	X	-
63 – 64	-	X	-



1608 Соединяемые контакты	Способ фиксации: И	
	Положение рукоятки	
	0°	+45°
1 – 2	-	X
3 – 4	-	X
5 – 6	-	X
7 – 8	-	X
9 – 10	-	X
11 – 12	-	X
13 – 14	-	X
15 – 16	-	X
17 – 18	-	X
19 – 20	-	X
21 – 22	-	X
23 – 24	-	X
25 – 26	-	X
27 – 28	-	X
29 – 30	-	X
31 – 32	-	X
33 – 34	X	-
35 – 36	X	-
37 – 38	X	-
39 – 40	X	-
41 – 42	X	-
43 – 44	X	-
45 – 46	X	-
47 – 48	X	-
49 – 50	X	-
51 – 52	X	-
53 – 54	X	-
55 – 56	X	-
57 – 58	X	-
59 – 60	X	-
61 – 62	X	-
63 – 64	X	-



Соединяемые контакты	Способ фиксации: Н (без ограничения хода рукоятки)							
	Положение рукоятки							
	-135 ⁰	-90 ⁰	-45 ⁰	0 ⁰	+45 ⁰	+90 ⁰	+135 ⁰	+180 ⁰
1 - 2	X	-	-	-	-	-	-	-
3 - 4	X	X	X	-	-	-	-	-
5 - 6	X	X	-	-	-	-	-	-
7 - 8	-	X	X	X	x	-	-	-
9 - 10	-	-	X	X	X	-	-	-
11 - 12	-	-	-	X	-	-	-	-
13 - 14	-	-	-	-	X	-	-	-
15 - 16	X	X	X	X	X	-	-	-
17 - 18	-	-	-	-	-	X	X	-
19 - 20	-	-	-	-	-	X	X	-
21 - 22	-	-	-	-	-	X	X	-
23 - 24	-	-	-	-	-	-	-	X
25 - 26	-	-	-	-	-	X	X	X
27 - 28	X	X	X	-	-	-	-	-
29 - 30	X	X	X	X	-	-	X	X
31 - 32	-	-	-	-	X	X	-	-
33 - 34	X	X	X	X	-	-	-	-
35 - 36	X	X	X	-	-	-	-	-
37 - 38	X	X	X	-	-	-	-	-
39 - 40	X	X	X	-	-	-	-	-
41 - 42	-	-	-	X	-	-	-	-
43 - 44	-	-	-	X	X	-	-	-
45 - 46	-	-	-	-	X	-	-	-
47 - 48	-	-	-	X	X	-	X	-
49 - 50	-	-	-	-	X	-	-	-
51 - 52	-	-	-	-	X	-	-	-
53 - 54	-	-	-	-	-	X	-	-
55 - 56	-	-	-	-	-	-	X	-
57 - 58	-	-	-	-	-	-	X	-
59 - 60	-	-	-	-	-	-	X	-
61 - 62	-	-	-	-	-	-	-	X
63 - 64	-	-	-	-	-	-	X	-